


0+400

$W=0,30 \text{ m}^2$

$N=0,58 \text{ m}^2$

$S_w = 1,74 \text{ m}$

$S_n = 1,08 \text{ m}$




0+500

$W=0,32 \text{ m}^2$

$N=0,44 \text{ m}^2$

$S_w = 1,80 \text{ m}$

$S_n = 1,04 \text{ m}$




0+600

$W=0,16 \text{ m}^2$

$N=0,46 \text{ m}^2$

$S_w = 1,30 \text{ m}$

$S_n = 1,22 \text{ m}$



0+700

$W=0,30 \text{ m}^2$

$N=0,20 \text{ m}^2$

$S_w = 2,00 \text{ m}$

$S_n = 2,44 \text{ m}$

